PATENT APPLICATION IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Application Serial No: 10/714,745	Attorney Docket No: BP2243CON
Application Filing Date: 11-17-2003	Inventor(s): Brian Campbell
Examiner: Tan, Vibol	
Art Group: 2819	Patent No: 6,822,482
Confirmation No: 4672	Patent Issue Date: 11-23-2004
Title: Dynamic scan circuitry for B-phase	_

Date: 10-31-2008

ATTN: Certificate of Correction Branch

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

After reviewing the issued U.S. patent referenced above, the Applicant notices one or more error(s) that was/were apparently made through the fault of the United States Patent and Trademark Office (USPTO).

The Applicant respectfully requests that the Director issue a Certificate of Correction, without charge to the Applicant, to be recorded in the records of U.S. patents.

The Applicant respectfully believes that no fees are due in accordance with 35 U.S.C. \S 254.

These corrections of the mistake(s) made by the USPTO are also depicted on the enclosed Certificate of Correction - Form PTO/SB/44 (09-07) (1 pg).

Errors made through fault of the USPTO.

Column 28, lines 27-28, in Claim 14: replace "circuits" with --circuit--.

The Office is invited to contact the undersigned by telephone or facsimile with any questions or concerns whatsoever.

RESPECTFULLY SUBMITTED,

MyxXShort/ Reg. No. 45,105

Shayne X. Short, Ph.D., Reg. No. 45,105

Direct Phone: (512) 825-1145

Direct Fax No. (888) 456-7824

GARLICK HARRISON & MARKISON ATTORNEYS AT LAW P.O. BOX 160727 AUSTIN, TEXAS 78716-0727

TELEPHONE (512) 825-1145 / FACSIMILE (888) 456-7824 or (888) 711-8305

Page __1__ of __1_

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number (Also Form PTO-1050

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

ISSUE DATE : 11-23-2004	
INVENTOR(S) : Brian Campb	ell
It is certified that an error is hereby corrected as shown b	appears or errors appear in the above-identified patent and that said Letters Paten pelow:
Column 28, lines 27-28, in Cla	nim 14: replace "circuits" withcircuit

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Garlick Harrison & Markison P.O. Box 160727

PATENT NO.

: 6,822,482 APPLICATION NO.: 10/714,745

Austin, TX 78716-0727 This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file

(and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.